



GE
Sensing

Sinsheimerstrasse 6
75179 Pforzheim
Germany

T + 49 7231 14335 0
F + 49 7231 14335 29

Rental Conditions Europe

Please Note !

GE Sensing needs this signed Rental Condition sheet together with the written purchase order prior to delivery

1. Rental Period:

- For EU countries, the minimum rental period is one week (for Kaye ValProbe™ logger systems minimum two weeks and for the calibration baths minimum four weeks)
- For Non-EU-countries, the minimum rental period is two weeks in general

2. Rental Order:

- GE Sensing needs a written purchase order in time before the system is needed. Otherwise GE Sensing can not guarantee to ship the system on schedule

3. Rental Rates and Pricing:

- See attached quote or rental information sheet
- First Invoice will be sent after the equipment is shipped
- If the unit is kept longer further invoices will be sent at the end of the months

4. Shipping, Handling and Installation:

- The customer is responsible for shipping charges to and from their facility
- GE Sensing always ship via UPS or DACHSER. It is highly recommended to return the same way
- The customer agrees that GE Sensing is not responsible for installation of the equipment
- **Minimum** Computer Specifications for Kaye Validator 2000 and ValProbe: **300MHz, 128MB RAM, Windows 2000** and one unused serial port (RS232)

5. Return of Equipment:

- The equipment has to be sent back directly to the GE Sensing office in Pforzheim, Germany
- The customer will receive a written RMA number (Return Material Authorisation) when the rental equipment is received. The equipment must be returned via this RMA number
- Together with the equipment the customer will receive a detailed check list with **all** items which will be delivered. This list has to be used for immediate checking of the shipment. Before the units will be returned to GE Sensing use this list to send back all equipment delivered. Any items not returned to GE Sensing will be invoiced
- The customer agrees, that GE Sensing can use the original purchase order number for any additional invoices.
- The equipment must be returned in its original packing containers or cases

6. Insurance:

- The customer agrees to insure the risk of loss or damage of the equipment while the equipment is in transit or while the equipment is at the customer's facility
- The customer agrees to exercise due and ordinary care in the placement, use, maintenance, storage, and accessibility of the equipment at their facility so as to ensure its safety and proper functioning



GE Sensing

Sinsheimerstrasse 6
75179 Pforzheim
Germany

T + 49 7231 14335 0
F + 49 7231 14335 29

7. Liability for Damage to Equipment:

- The customer will return the equipment at the end of the rental period in good condition with no excessive wear and use
- The customer will be responsible for all charges incurred by GE Sensing to service and repair the equipment to any excess wear and use. Excess wear and use includes, among other things 1) physical damage broken or missing parts or accessories, 2) missing Manuals or Software, 3) the equipment does not work as represented. Or if the equipment is materially unsatisfactory for any other reason

without full completion of this form the order can not be proceeded.

Start of Rental Period

Estimated length of Rental Period

We will always invoice every started calendar week. This means if you require the unit at your site on a Wednesday we will charge you for the full week. After the end of the Rental Period the Unit/s will have to be returned to Pforzheim, Germany latest by the following Tuesday by end of Business. If you fail to do so we will charge you again the full calendar week.

Invoice Address:

Shipping Address:

Stamp / Company Name

Date

Name / Title

Signature

➤ If you rent a **Validator** or **ValProbe** please specify desired Software Version: _____

➤ If an **IRTD** or **ValProbe** logger has been rented, you will receive a verification report after return of the units.

Send Verification report to E-mail address: _____